


Method Statement no. 7

**GECOL ELECTRICAL Co. – TOBRUK (LIBYA)**

**PUMP STATION REPAIRS.**

**UNDERWATER AND WET AREA REPAIRS OF CONCRETE PILES WITH EPOXY  
MORTAR FORMED BY SUBCOM 150 AND GRADED QUARTZ SAND.**



The missing original concrete has been replaced underwater and on wet areas by an epoxy mortar formed by SUBCOM 150 and graded quartz sand, poured in formworks sealed with SUBCOM T.260.

**Sinit Intermar S.r.l. - Via V. Chiarugi, 76 – 45100 Rovigo (Italy)**

Tel. +39 0425 361961 – Fax +39 0425 410115

E-mail: [sinit@tin.it](mailto:sinit@tin.it) – [info@sinitworks.com](mailto:info@sinitworks.com)

[www.sinitworks.com](http://www.sinitworks.com)